

MAINTENANCE GUIDE

Legacy, Outback, Impreza and Forester models 1995 and up.

Interval

Services performed

Recommended Time

0.4 hours

Every 6,000 km

- Replace engine oil and filter
- Inspect and adjust all fluid levels including both differentials
- Inspect and adjust all tire pressures
- Inspect operation of all lights, wipers and washers
- Inspect and adjust clutch clearance (if applicable)
- Inspect and adjust drive belt tension
- Clean and lubricate power antenna mast (if applicable)
- Inspect axle boot condition
- Lubricate all latches, hinges & locks (hood, doors, fuel door & trunk lid)
- Road test vehicle

At 24,000 km

All items listed at "Every 6,000 km service" plus:

2.0 hours

- Replace air filter(s) and fuel filter
- Rotate tires and inspect for wear. Perform wheel alignment if necessary. (Additional charge)
- · Lubricate all weather strips including sun roof
- Service and lubricate front and rear calipers
- Inspect brake pads and linings
- Inspect, service and adjust parking brake system
- Inspect all steering and suspension components
- Inspect and service battery cables and terminals
- Test engine coolant and inspect hoses and clamps
- Reset Engine Control Management System

At 48,000 km

All items listed at 6,000 km and 24,000 km services plus:

3.5 hours

- Replace engine coolant
- Replace spark plugs (SOHC engine only)
- Inspect accessory drive belt(s)
- Replace PCV valve
- Inspect all hydraulic brake and clutch lines
- Replace brake fluid
- Inspect all emissions related hoses and connections
- Inspect and clean EGR valve and passages (if applicable)

At 72,000 km

All items listed at 6,000 km and 24,000 km services plus:

2.5 hours

- Replace transmission fluid, automatic and standard
- Replace front (AT only) and rear differential oil Under severe conditions replace fluids at 48,000 km

At 96,000 km

All items listed at 6,000 km, 24,000 km and 48,000 km services plus:

Replace spark plugs (SOHC and DOHC engines)

Replace camshaft drive belts on 1999 and prior models (Add 2.0 hours)

At 168,000 km

At items listed at 6,000 and 24,000 km services plus:

3.0 hours

3.5 hours

- Inspect valve clearance on all solid lifter engines (Adjust if necessary at additional charge)
- Replacement of camshaft drive belts on 2000 and newer models (Add 2.0 hours)

To obtain your cost, multiply the dealer hourly labour rate by the number of hours stated on this poster and add the cost of all necessary parts.